

From


**The Executive Engineer
Provincial Division
PWD Amethi.**

To,

**The Principal
St. Marry Senior Secondary Convent School
Jamon, Amethi.**

Sub- School Building Safety Certificate for the Year 2023-24

The Assistant Engineer, Provincial Division, PWD Amethi has reported this office that the building of St. Marry Senior Secondary Convent School Jamon Gauriganj Amethi has been inspected physically and found the same structurally safe with the reporting of Architect and Construction Engineer and fit are human habitation for the year 2017-18. Necessary proforma No. I & II are enclosed herewith your information and further necessary action. NOC issued subject to condition that land use certificate may obtained from client department and school should be sanctioned by the competent authority.


Executive Engineer
Provincial Division,
PWD Amethi,
20/06/23

Dated - 20.06.2023

Endst No. 1674/1 काम

Copy- Assistant Engineer, Provincial Division PWD Amethi for information .


Executive Engineer
Provincial Division,
PWD Amethi

PROFORMA FOR THE SAFETY CERTIFICATE OF SCHOOL BUILDING

(PART-I)

(To be filled by the head of the school/Institute)

- 1- Name of the School :- *St-Mary Senior Secondary School*
- 2- Location :- *Jamon Anethi*
- 3- Plot Area :- *197400 Sqm.*
- 4- Plinth Area :- *125000 sqm*
- 5- No of Stories :- *2 stories*
- 6- Area of Constructed Part of the Building :-
If the building has been constructed under the supervision of the qualified Engineer
- 7- The following details may be given-
- a) Name of Engineer with qualification :- *Mr Sanjay Singh (B.tech)*
- b) Address of The Engineer :- *Hargaon Jamon*
- c) If structural drawing used in construction if available? :-
- d) Name and address of Architect with qualification :- *Brijesh Jugdish pur, Gauriganj*
- 8- Whether the building has been constructed for the purpose of
- a) School Yes / No
- b) Residential Purpose and use for the school Yes / No
- 9- Material used for Roofs
- a) RCC slabs. Yes / No
- b) RS Joists batons Yes / No
- c) Wooden Joints Bottom Yes / No
- 10- Material used for Wall
- a) Mud Mortar Yes / No
- b) Cement Mortar Yes / No
- c) Lime Mortar Yes / No
- 11- Flooring
- a) Conglomerate Yes / No
- b) Terrace Yes / No
- c) Brick Paving Yes / No
- 12- A detail drawing indicating the doors along with windows and location Fitting and windows is attached
- 13- FOR FIRE SAFETY
- a) Whether the width of the stair case is 1.5mtr. Yes / No
- b) Whether Portable Fire extinguisher exits. Yes / No
- c) Whether school building free from inflammable & toxic material. Yes / No
- d) Whether cooking of food is done at a safe place. Yes / No
- 14- Requirements for fire protection arrangements under NB-Part-IV Yes / No




PART-II

(To be filled by the SDE of PWD (B&R) Department)

- (a) I have visited the above mentioned school On dated 19.06.2023 And have visually inspected from all angles of safety and find it fit for normal use as school building.
- (b) In case any addition/alteration or expansion and modification to this buildings is to be carried out the same be carried out under the supervision of a qualified Engineer and this certificate may be re-obtained after the completion from the under signed.
- (c) In case the building is affected by flood or if there is settlement of walla foundations or sagging of roofs etc. immediate inspection of the undersigned be arranged to check the stability and safety of the building.
- (d) This building can be safety occupied for the normal use up to (indicate which it can be used) ...19.06.2023.....

સહાયક


સહાયક જમિયત્તા
પ્રાન્તીય ખબ્ડ લોનિવિ
અમેઠી